




Photograph #7, taken 4/19/2003. The west-side skimmer drive rod, as pictured, was the location of VOC emissions.



Photograph #8, taken 4/19/2003. Location of vapor leak at the overlap of three bolted plates on the roof of the water injection tank (Item #6, Permit R-D93078, A/N 306537)