



Photograph #9, taken 4/19/2003. The bull plug, as denoted by the arrow, was resting on top of an open threaded connection, allowing VOC emissions from Flange #1412, which is at the top of the external water level boot of the water injection tank.